

1 / 18

FIG. 1





FIGURE 1A-67200

FIG. 2



2 / 18

FIG. 3






FIGURE 5 PULSE WIDTH

FIG. 5



10821776160

FIG. 4



4 / 18

FIG. 6





FIG. 21F-515650

FIG. 7



5 / 18

FIG. 9




FIG. 10




FIG. 11





FIG. 12



7 / 18

FIG. 8




FIG. 13





FIG. 14



8 / 18

FIG 15




FIG 16 (a)





FIG 16 (b)



TE0921T F 6712416660

9 / 18




FIG. 17




FIG. 18




FIG. 19 (a)




FIG. 19 (b)

10 / 18




FIG. 23






FIG. 24



10032154-612746550


11 / 18

FIG. 21




0506147157-112804

FIG. 22




12 / 18

FIG. 25




TOP SECRET 67200

FIG. 26




13 / 18

FIG. 27




108211-5 P246660

FIG. 28



14 / 18

FIG. 29



20082117-51F241550

FIG. 30




FIG 31 (a)





FIG 31 (b)



20021117-512415650

FIG. 32




FIG. 33
(PRIOR ART)





FIG. 34
(PRIOR ART)



18 / 18

FIG. 35
(PRIOR ART)

AMOUNT OF PROJECTION OF GLASS CLOTH





FIG. 36
(PRIOR ART)

DAMAGE TO TOP COPPER FOIL



2023 RELEASE UNDER E.O. 14176